HIGHWAY IMPROVEMENT PLAN – Stage 1			ACTION PLAN – Stage 2		
Priority	Location	Problem and suggested remedy	Cost Estimate	Funding Source	Action/Programme (Who/When)
1.	A229 through Staplehurst village	Vehicles speeding through the village  This is a 30mph speed limit and parish council would like to investigate the possibility of speed cameras		Parish Council/County Member	Traffic survey carried out by PC – Results received – Met with parish council – 13 March 2019 to discuss results.  Site visit carried out to look at potential traffic calming measures.  23/5/19 - Quote sent to parish council for preliminary design  (see point 3 below)
2.	George Street/A229	Issue with commuter parking Would like to consider DYL's	£2965 for TRO	??	KCC and MBC carried out joint site visit – No safety issues found so no action – informed parish council
3.	Gateway Improvements in Cranbrook Road / Church Hill	Speeding at southern approach.  SPC working group discussed proposals made in response to 1 above. Requests estimate for the installation of three of the suggested improvements: dragons' teeth markings, 30mph roundel road marking and rumble strips. Issue for Group is that on this approach there is already a lot of physical street furniture; more would be distracting for motorists		ксс	<ul> <li>Gateway features and new village nameplate</li> <li>Roundels</li> <li>Rumble strips</li> <li>Dragons teeth</li> <li>To be monitored once implemented to see if 30mph limit can be extended, particularly on Church Hill</li> <li>03/02/20 – SPC Full Council formally supported the submitted plans.</li> <li>13/02/20 – JW advised that funding bid had been successful. JW will update on progress.</li> <li>19/5/20 – Scheme due to be delivered this financial year 2020/21 – Still to be designed</li> </ul>
4.	Speed Limit Thresholds on A229 south of village	Excessive speed on A229 south of village.		??	See above  19/5/20 - No further updates - Still to be investigated.

HIGHWAY IMPROVEMENT PLAN – Stage 1			ACTION PLAN – Stage 2		
Priority	Location	Problem and suggested remedy	Cost Estimate	Funding Source	Action/Programme (Who/When)
		From Cranbrook to Staplehurst there are many threshold changes. 20mph at Cranbrook School becomes 40mph near the junction with A229 and the subsequent roundabout. There is a short 50mph section until 40mph at Rock Hill, followed by 50mph at Knoxbridge. As Staplehurst is reached it changes to 40mph and then again to 30mph.  Suggestion: a consistent 40mph limit from Rock Hill to the 30mph Staplehurst threshold (moved to south of Pinnock Lane). Information note: in Knoxbridge there are bus stops, housing, businesses and many slowlorry movements. The soon-to-becreated Fridays' road system will add another junction used by slow-turning juggernauts. SPC has supporting data from Streetwise survey (Nov. 2018).			Speed survey to be carried out which are currently on hold due to Covid-19
5	Roads near Staplehurst school (area edged by Offens Drive and Bathurst Road)	Perceived speeding on roads near the school, Surrenden Field and Pope Drive amenity space.  Suggested remedy: 20mph limit. SPC has asked KCC to consider it for selection as pilot study. SPC has drawn up a proposed area and is consulting residents.		KCC pilot budget.	Update to be provided to PC with process  27/02/20 – JW advised process will be  • Stage 1 – establish community support via consultation (SPC has done)  • Stage 2 – undertake traffic surveys (may be chargeable)  • If 1 & 2 are ok, KCC will price up a scheme and discuss funding  • Scheme agreed and installed  • Post-installation monitoring  JW also advised that KCC is assessing requests to

HIGHWAY IMPROVEMENT PLAN – Stage 1			ACTION PLAN – Stage 2		
Priority	Location	Problem and suggested remedy	Cost Estimate	Funding	Action/Programme
				Source	(Who/When)  participate in the pilot. No timescales available, but will update 'shortly'  19/5/20 — No further update — Speed surveys to be carried out (funded by KCC) which are currently on hold
6	Gybbon Rise corner at junction of school entrance and Bower Walk.	Issues caused by dangerous parking, especially at school arrival and departure times.  SPC would like to investigate feasibility of single or double yellow lines. Plans to consult residents and school.		??	Assessment to be carried out – If not successful continue to monitor.  Update from JW awaited. This will inform nature of local consultation.  19/5/20 – No further update – Assessments due to take place Summer 2020 (TRO's currently on hold due to Covid-19)
7	Country Lanes — A - Five Oak Lane	Vehicle speed / narrow / blind corners / 60mph  Plastic kerbs / bollards / reflectors / convex mirrors / vegetation trimming / passing places			Parish Council to log on WAMS
8	A229 – A - Station Road near traffic Lights B – Bus stop opposite Pinnock Lane	Footpaths too narrow for pedestrian safety  Widen footpath by reducing A – opposite footpath B – opposite white line hatching			A – On site assessment to be carried out by KCC  B – Check with Bus Stop Team to see if this has been raised before (possibly move bus stop)  27/01/20 – JW advised little can be done. Adjacent land is privately owned.  19/5/20 – Update from Transport Team who are not keen on moving the bus stop as it is quite a distance from the existing location. They confirmed they have not had any previous complaints about this.
9	Marden Road roundabout	Sight lines are misleading			Section 278 Scheme – Clairemarie Vine to provide

HIGHWAY IMPROVEMENT PLAN – Stage 1			ACTION PLAN – Stage 2		
Priority	Location	Problem and suggested remedy	Cost Estimate	Funding Source	Action/Programme (Who/When)
		A - chevrons to indicate south side kerb leads to roundabout would block direct vision along road from both directions			update 27/01/20 – JW has asked Developments Agreement Team to provide an update. Still awaited.  19/5/20 – Emailed Dev. Agreements for update.
10	Hawkenbury Bridge	Single lane, humpback, with no visibility of oncoming traffic. History of accidents, incidents and aggressive driving. Suggested: install solar-powered traffic signals, activated by vehicle movement. If deemed safer, position southern light at brow of railway bridge.	??	??	Liaise with Headcorn PC because bridge is on Staplehurst-Headcorn boundary. Location is thought to be in Headcorn PC's HIP. Clerk has asked Headcorn PC to confirm.  HPC confirms it is in its HIP (item 12) and that it is supportive of SPC's position.  19/5/20 – No further update at present. Will look at in the future
11	Station Road pedestrian crossing	Station Road pedestrian crossing – SPC seeks clarity on delivery of the crossing which is a planning obligation of both the Bovis and Sainsbury's developments		Developers' planning obligations.	JW has contacted Claremarie Vine who will update with progress. Update awaited.  26/5/20 – JW has advised that Sainsbury's has proposed to provide a puffin crossing outside Trinity Court and a mini-roundabout at the new access with informal crossing points. Sainsbury's development will provide the pedestrian crossing the parish wishes to see implemented.